

USB Driver Readme

Please follow the instructions below to install the driver onto your computer.

1. Turn on the instrument, and connect the USB cable from the instrument to the computer.
2. Go to **"Device Manager"**.
 - a. On Windows 7, click the Windows Menu icon on the bottom left of the screen and right-click **"Computer"** and select **"Properties"**. Then, on the left column, click on the link that says **"Device Manager"**.
 - b. On Windows XP, right-click on **"My Computer"** and select **"Properties"**. Then, select the **"Hardware"** tab and click on **"Device Manager"** button.
3. Locate the USB virtual Com device from the **Ports and LPT** list. It will be named **"BK Virtual ComPort"**.
4. Right-click on it and select **"Update driver..."**. Then, select **"Browse my computer for driver software"** or select to manually update the driver from a specific location.
5. Then, locate the directory where you downloaded the driver file (in the same directory as this instruction readme) and look for the file name **"bkpcdc.inf"**. You can also search within the same folder for Windows to search for the file for you.
6. You may be prompted with a warning saying that the driver has not been digitally signed. Proceed to select **"Install anyway..."** to continue the installation process.
7. Afterwards, go back to the **"Device Manager"** and you will see a COM port assigned to **"BK Virtual ComPort"**. Use the COM port number when remotely communicating with the device via USB.