

PC LINK Software Package

QUICK STARTING GUIDE

Copyright © 2004-2005 BW. All rights reserved.
This guide provides an overview of the PC LINK software.
Detail user's Instruction is available on the HELP file of the software.
All the trademarks belong to their respective proprietors.

P/N: 91-27011-1

1. Introduction

The purpose of this software is to enable the user to remotely control the meter. This software also adds datalogging capability to the meter.

Installing this software will not affect the electronic characteristics, the specifications, the functions, and the operations of the instrument. After installing the software, user will have the options of using the instrument by itself or using it with PC through a communication port. For instrument set-up and operation, please refer to the instrument's OPERATION MANUAL.

2. Minimum PC Requirements

For smooth operation, user's computer has to be the following:

- a. Win 98/Me/NT/2000/XP OS with IE 5.01 or later
- b. Microsoft Excel 2000 or later
- c. Pentium II/300MHz PC with CD-ROM
- d. 40MB HD free space
- e. 128MB RAM
- f. USB port

3. Hardware Connections and Software Installations:

3.1 Hardware Connecting and USB Driver Installation:

- a. Connect the USB connector of the cable to an available USB port on your computer and the other end of the cable connects to the instrument.
- b. The computer will find the USB cable and remind you to install the USB driver of the device. Insert CD, then choose the path “\USB-Serial Cable driver” and click “OK” button to install the driver.
- c. The computer is added a virtual RS-232 COM port when the user completes all installation processes. User can check the COM status from the Control Panel of the Windows OS.

3.2 Application Software Installation:

- a. Insert PC LINK accessory CD into CD-ROM. The software will execute installation automatically. If the software does not execute automatically, at the bottom of left hand corner, select **Start** -> **Execute** -> **Browse** -> **CD-ROM Location** -> select “**setup.exe**” -> **Open File** -> **Execute**.
- b. User may decide the software installation location or use the preset location:\Program Files\PC LINK\. Select “Next” to run installation or select “Cancel” to abort installation.
- c. When the installation is completed, select “Finish” to complete the installation process.
- d. After installation is completed, user can execute the program immediately without restarting the computer.
- d. Please remove the older version software firstly

and then re-install the software if you want to update the software.

4. Software Executing:

At the bottom left hand corner of the screen, select **Start** -> **Programs** -> **PC LINK** to run the program.

5. Software Uninstallations:

Insert PC LINK accessory CD into CD-ROM again. The software will execute un-installation automatically. If the software does not execute automatically, at the bottom of left hand corner, select **Start** -> **Execute** -> **Browse** -> **CD-ROM Location** -> select “**setup.exe**” -> **Open File** -> **Execute**. User may:

- a. Select “Cancel” to abort uninstalling, or
- b. Select “Next” to continue uninstalling. Last, select “Finish” to complete the uninstalling procedure.

6. Features:

- a. Manual or automatic recording
- b. Maximum 65525 records
- c. Record time interval 00:00:01 ~ 99:99:99
- d. Saving *.csv data format
- e. Manual or programmable output control (some model provided)